

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402790052

Date Received:
08/24/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mike Storey

970-939-6353

mstorey@bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699104278

Inspection Date: 08/17/2021

FIR Submit Date: 08/18/2021

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 431774

Location Name: Wetco Farms Number: A-4 Pad County: _____

Qtrqr: NWN Sec: 4 Twp: 4N Range: 63W Meridian: 6
W

Latitude: 40.347739 Longitude: -104.451608

FACILITY - API Number: 05-123-00 Facility ID: 431774

Facility Name: Wetco Farms Number: A-4 Pad

Qtrqr: NWN Sec: 4 Twp: 4N Range: 63W Meridian: 6
W

Latitude: 40.347739 Longitude: -104.451608

CORRECTIVE ACTIONS:

1 ☒ CA# 154950

Corrective Action: Comply with Rule 606.

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/24/2021

Operator
Comment:

Weeds have been removed in complinace with Rule 606.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 154951

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/19/2021

Operator
Comment: Risers marked with OOSLAT per Rule 1105.b

COGCC Decision: **Not Approved**

COGCC
Representative: Not all unmarked risers were marked.

3  CA# 154952

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/24/2021

Operator
Comment: Oily waste has been removed in accordance with 905.e

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4  CA# 154953

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/24/2021

Operator
Comment: Oily waste has been removed in accordance with 905.e

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5  CA# 154954

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 08/27/2021

Response: CA COMPLETED

Date of Completion: 08/24/2021

Operator
Comment: Oily waste has been removed in accordance with 905.e

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed:

Title: Regulatory Analyst

Date: 8/24/2021 1:10:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402790052	FIR RESOLUTION SUBMITTED
402790096	Compliance Photos
402790100	Compliance Photos

Total Attach: 3 Files