

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2021

Submitted Date:

08/27/2021

Document Number:

696203091**FIELD INSPECTION FORM**Loc ID 383264 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
383264	LOCATION	AC			-	CC 0610-21-41 Pad	RI

**General Comment:**

On 8/23/2021, On 7/12/2021, Reclamation Specialist Trujillo conducted an interim reclamation inspection at Laramie Energy's CC 0610-21-41 Location in Garfield County, Colorado.

This inspection is also a followup to #696202108, #696202674 and #696202922 to document compliance with the following corrective actions:

34-60-121(1) CRS-b: Permit Violation  
1003/1004: Interim and Final Reclamation

It was observed in this inspection that the Location remains out of compliance with COGCC Permit Conditions, Rules and Corrective actions; Location has been out of compliance with COGCC 1004 Rules and corrective actions since 2013; Location is being referred for enforcement.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

## RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

## 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment [See "COGCC Comments" for comments regarding reclamation.](#)

Corrective Action **Original Corrective Action and Date remains applicable:**

Date **02/13/2019**

**Operator is directed to either immediately**

**1) Comply with the "Notice to Operators: Interim Reclamation Procedures for Delayed Operation (dated January 5, 2017)" and permit conditions. NOTE: Variances are no longer able to be submitted with a Form 4 Sundry, but now require a hearings application to the commission per Rules 502 and 510.**

**or**

**2) Perform final reclamation of the Location**

Overall Interim Reclamation **Fail**

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: **RANGELAND**

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment

User

Date

**RECLAMATION COMMENTS**

trujilloam

08/27/2021

Location originally constructed in 2005 by Oxy. Laramie took ownership of Location 3/1/2016. FIRs #680101328 dated 12/14/2016 and #680102390 dated 11/03/2017 required Final Reclamation by 7/1/2017; Operator failed to comply with 1004 Rules and Corrective actions.

Laramie received permits for both the Location (Form 2A 402598341), and wells on 2/13/2019. Form 2 Permit conditions required that Operator shall comply with Notice to Operators: Interim Reclamation Procedures for Delayed Operation (dated January 5, 2017)

Inspection #696202108 dated 12/8/2020, #696202674 dated 5/14/2020 and #696202922 dated 7/12/2021 observed that no drilling or subsequent operations have commenced. Additionally, no "Delayed Operations NTO" request was submitted and approved per permit COAs. Inspections required Operator to either comply with the NTO, or perform 1004 final reclamation.

It was observed in this inspection that this Location remains out of compliance with the Permit Conditions/Delayed Operations NTO, COGCC Rules and Corrective actions; Operator has neither performed the reclamation, or received a variance request for Delayed Operations.

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203105	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517952</a>