

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/27/2021

Submitted Date:

08/30/2021

Document Number:

693700855**FIELD INSPECTION FORM**
 Loc ID 317496 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 42950Name of Operator: INDUSTRIAL GAS SERVICES INCAddress: 4891 INDEPENDENCE ST STE 200City: WHEATRIDGE State: CO Zip: 80033**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		igsinc@att.net	
Petrie, Erica		erica.petrie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238354	WELL	SI	05/01/2016	GW	123-05198	BEHRING 1	EI

**General Comment:**

COGCC Environmental Staff Inspection focused on Remediation Project 7910.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds have overgrown berms around tanks.		
Corrective Action:	Comply with Rule 606 to control weeds		Date: 09/13/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Oily waste/oil impacted soil is present around wellhead from historical spill(s)			
Corrective Action:	Remove oil impacted soil and dispose concurrent with oily soil from pit closure. Provide soil sample from wellhead cleanup, analyzed for total petroleum hydrocarbons (TPH C6-C36) and include documentation with Form 27 Supplemental documenting removal of oily waste for Remediation Project 7910.			Date: 10/31/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Flow Line	#			
Comment:	Flowlines from Heater Treater to pit must be abandoned in accordance with Rule 1103. Contact Engineering Integrity Supervisor Mark Schlagenhauf, mark.schlagenhauf@state.co.us, for questions/guidance on flowline abandonment.			
Corrective Action:	Properly abandon flowlines to former pit. Comply w/ Rule 1103. Original Corrective Action date: 03/20/2017.			Date: 03/20/2017

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PLASTIC AST		40.440350,-104.170070	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	<input type="text"/>	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Berms have eroded,			

Corrective Action:	Restore secondary containment berms around produced water tank per Rule 603.e. Corrective Action date concurrent with site work to complete Remediation 7910	Date:	10/31/2021
--------------------	---	-------	------------

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



## Environmental

### Spill/Remediation:

Comment: Met Operator onsite to discuss final sampling of land treatment area and commence hauling impacted material for offsite disposal of oily waste as outlined in Form 27 Supplemental Document #402763706.

Corrective Action: Comply with conditions of approval and deadlines listed on Form 27 Supplemental Document #402763706.

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_