

Location ID: 426135

[illegible]

Photo 1. Photo of Form 21 as filled out in the field. MIT failed in the field.

Photo 2. Pressure on casing. Operator unable to bleed to 0 psi so test timer never started.