

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:
 402783428
 Date Received:

OGCC Operator Number: 10633 Contact Name: Mark Balderston
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (970) 629-5846
 Address: 1801 CALIFORNIA STREET #2500 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: mark.balderston@crestonepr.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____
COGCC contact:

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-001-06536-00
 Well Name: FLADER INDUSTRIES INC Well Number: B-1
 Location: QtrQtr: NWNW Section: 34 Township: 3S Range: 65W Meridian: 6
 County: ADAMS Federal, Indian or State Lease Number: _____
 Field Name: WILDCAT Field Number: 99999

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.752631 Longitude: -104.657067
 GPS Data: GPS Quality Value: _____ Type of GPS Quality Value: PDOP Date of Measurement: 07/19/2021
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	xx	23	0	227	200	227	0	VISU
1ST	7+7/8	7	P110	26	0	871	512	871	0	VISU
OPEN HOLE	7+7/8				871	8780				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	67	sks cmt from	7687	ft. to	7487	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	166	sks cmt from	2987	ft. to	2702	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	251	sks cmt from	2017	ft. to	1450	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	181	sks cmt from	1397	ft. to	1079	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	2	sks cmt from	6	ft. to	0	ft.	Plug Type:	CASING	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 236 sacks half in. half out surface casing from 1057 ft. to 6 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug
Surface Plug Setting Date: 07/31/2021 Cut and Cap Date: 08/09/2021 to Capping or Sealing the Well: 9

*Wireline Contractor: _____

*Cementing Contractor: Schlumberger

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Notice of plugging provided via Form 42 Doc 402745401.
Confirmed static conditions after placing plug @ 7700'.
Well was static prior to placing plug at 1070'.
Cement was pumped from 1070' to surface with full returns throughout.
Each plug exceeds 100' of cement.
Crestone Peak Resources engineer was in communication with COGCC regarding any changes made to the procedures stated in the Plugging Procedures section of the approved Form 6 NOI.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Jane Washburn

Title: Sr Prod Engineering Tech

Date: _____

Email: jane.washburn@crestonepr.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

<u>COA Type</u>	<u>Description</u>

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402794983	CEMENT JOB SUMMARY
402794996	OPERATIONS SUMMARY
402795148	OTHER
402795248	WELLBORE DIAGRAM
402795287	OPERATIONS SUMMARY

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Requested GPS data to meet COA RTD	09/01/2021

Total: 1 comment(s)