



---

**RE: Suckla Farms E#2 flowline spill 479834, Remediation Project 19028**

1 message

**Max Knop** <MKnop@kpk.com>

Tue, Aug 31, 2021 at 11:59 AM

To: Peter Gintautas <peter.gintautas@state.co.us>, COGCC <COGCC@kpk.com>

Hi Peter,

Thank you for the notification. A vac truck will be sent to the location today to address the observed free product.

Regards,

Max

**Max Knop** | K.P. Kauffman Company, Inc.

1675 Broadway, Suite 2800 | Denver, CO 80202 | T: (303) 825-4822 | [mknop@kpk.com](mailto:mknop@kpk.com) | [www.kpk.com](http://www.kpk.com)

---

**From:** Peter Gintautas <[peter.gintautas@state.co.us](mailto:peter.gintautas@state.co.us)>

**Sent:** Tuesday, August 31, 2021 10:12 AM

**To:** Max Knop <[MKnop@kpk.com](mailto:MKnop@kpk.com)>; COGCC <[COGCC@kpk.com](mailto:COGCC@kpk.com)>

**Subject:** Suckla Farms E#2 flowline spill 479834, Remediation Project 19028

Max,

I observed free product floating on what appears to be groundwater in the open excavation at this spill site this morning.

The corrective action matrix provides that removal of free product must be accomplished in 24 hours.

Control and contain spills/releases and clean up per Rule 912.a.

If water in excavation is groundwater then actions must be taken to report impacts to groundwater as described in Rule 912.b(1)F.

I will enter an inspection for this spill later today.

Peter

**Peter Gintautas Ph.D.**  
Environmental Protection Specialist - Northeastern Colorado

Cell 719.679.1326

[peter.gintautas@state.co.us](mailto:peter.gintautas@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)  co\_dnr\_div\_ogcc\_rgb\_email 2

**Please be cautious**

KPK External Sender Notice: This email is from an external sender. Please exercise caution when opening attachments or clicking links.

**Please be cautious**

KPK External Sender Notice: This email is from an external sender. Please exercise caution when opening attachments or clicking links.