

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402794464

Date Received:
09/03/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10720
Name of Operator: KODA EXPLORATION LLC
Address: 2443 SOUTH UNIVERSITY BLVD 215
City: DENVER State: CO Zip: 80210

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>SULLIVAN RYAN</u>		<u>rsullivanvc@gmail.com</u>
<u>ELGERD ANDERS</u>		<u>elgerd@comcast.net</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201987
Inspection Date: 08/23/2021 FIR Submit Date: 08/25/2021 FIR Status: _____

Inspected Operator Information:

Company Name: KODA EXPLORATION LLC Company Number: 10720
Address: 2443 SOUTH UNIVERSITY BLVD 215
City: DENVER State: CO Zip: 80210

LOCATION - Location ID: 472992

Location Name: Roaring Fork Number: 14-28 Pad County: LINCOLN
Qtrqtr: SESW Sec: 28 Twp: 16S Range: 54W Meridian: 6
Latitude: 38.627090 Longitude: -103.460720

FACILITY - API Number: 05-073- -00 Facility ID: 472941

Facility Name: Roaring Fork Number: 14-28
Qtrqtr: SESW Sec: 28 Twp: 16S Range: 54W Meridian: 6
Latitude: 38.627090 Longitude: -103.460720

CORRECTIVE ACTIONS:

1 CA# 155179

Corrective Action: Comply with 1002.c Date: 09/15/2021

Response: CA COMPLETED Date of Completion: 09/15/2021

Operator Comment: Topsoil piles have been hydromulched to ensure stabilization. The most recent stormwater inspections have not indicated any erosion of the topsoil berms. Weeds will be mowed where necessary and as close to the top soil berms as possible by 9/15/21. Mowing the hydromulched topsoil berms is not recommended as that will destroy the protective hydromulch and compact the stored top soil. The weed growing season is coming to an end and many of the weeds are already dead/dormant, dying or will be dead in the next 2-3 weeks per a meeting on site

with a local landowner/farmer/agronomist on 9/2/21. The agronomist recommended not spraying weeds this time of year since many are already dead/dormant as it will not do any good. Instead, he recommended delaying weed spraying until spring when the growing season begins. As a test, the few living weeds were spot sprayed on the 0.5 acre reclaimed area on 9/2/21.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 155180

Corrective Action: Comply with Rule 1003.a and Rule 606.

Date: 09/15/2021

Response: CA COMPLETED

Date of Completion: 09/15/2021

Operator Comment: Equipment on site will be removed by 9/15/21.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 155181

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 05/17/2021

Response: CA COMPLETED

Date of Completion: 05/19/2021

Operator Comment: The location has undergone interim reclamation consistent with the approved Form 2A (doc #402149030) and the approved Form 27 (doc #402706133). No further interim reclamation will occur on the site as Koda plans to P&A the well and perform final reclamation of the site by Nov 1, if possible.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Del Hierro

Signed: _____

Title: Regulatory Agent

Date: 9/3/2021 2:42:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files