

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE <small>LLC</small>	
G e n e r a t o r	Generator's Name and Mailing Address: Tap Road			Manifest No.: 126363		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048	Facility Phone No.: (970) 889-0006		
	Well or Site Name: Hole Pad			Truck/Haul Container	Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:			No.: Lone LT 413	Type: TAN	1452 TONS
	Lat/Long:					
	Waste Name/Waste Type:					
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
T r a n s p o r t e r	Transporter Acknowledgement of Receipt of Materials					
	Transporter Company Name: Lone Tree Services		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name:		Signature:			Date: 6-10-21
D i s p o s a l F a c i l i t y	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
	Printed/Typed Name: Kerava Dill		Signature: <i>[Signature]</i>			Date: 6-10-21

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE	
Generator's Name and Mailing Address: Tap Road				Manifest No.: 126351		
Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006		
Generator's Name and Mailing Address: Designated Facility Name and Site Address: Well or Site Name: AFE#/ Lat/Long: Waste Name/ Special Handling Instructions: Generator's Certification: Printed/Typed Name: Signature: Date:	Well or Site Name: Hate Parl.		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/ Lat/Long:		No.: Lone 4719	Type: SD	0377	TDS
	Waste Name/Waste Type: (cont. Soil)					
	Special Handling Instructions:					
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials Transporter Company Name: Printed/Typed Name: Signature: Date:	Transporter Company Name: Lone Tree Services LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Felipe Garcia		Signature:			Date: 6-10-21
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Discrepancy Indication Space: Waste Load Rejection Reason: Facility Owner or Operator: Printed/Typed Name: Signature: Date:	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
	Printed/Typed Name: Kendra		Signature:			Date: 6-10-21

NON-HAZARDOUS WASTE MANIFEST <i>Tap Road</i>		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE	
Generator	Generator's Name and Mailing Address:			Manifest No.: <i>715020</i>		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048	Facility Phone No.: (970) 889-0006		
	Well or Site Name: <i>Hole Pad</i>			Truck/Haul Container	Total Quantity	Unit/Wt/Vol
	AFER/Reference#:			No.: <i>2719</i>	Type: <i>SD</i>	<i>2179 TONS</i>
	Lat/Long:			Waste Name/Waste Type: <i>(cont. Soil)</i>		
	Special Handling Instructions:			Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste		
Transporter	Printed/Typed Name:		Signature:	Date:		
	Transporter Acknowledgement of Receipt of Materials					
	Transporter Company Name: <i>Lone Tree Services, LLC</i>		US EPA ID No.:	Transporter's Phone No.: (include area code)		
Disposal Facility	Printed/Typed Name: <i>Fraser Johnson</i>		Signature:	Date: <i>6-10-21</i>		
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) <i>Lone Tree Services, LLC</i>					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above						
Printed/Typed Name: <i>Kendra Hill</i>		Signature:	Date: <i>6-10-21</i>			

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE LLC	
Generator's Name and Mailing Address: Tap Root				Manifest No.: 126364		
Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006		
G e n e r a t o r	Well or Site Name: Hole Pool		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE# / Reference#:		No.: 43	Type: TAN	1524	RUS
	Lat/Long:		Waste Name/Waste Type: Coal Soil			
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
T r a n s p o r t e r	Transporter Acknowledgement of Receipt of Materials					
	Transporter Company Name: Lone Tree Services		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name:		Signature:			Date: 6-10-21
D i s p o s a l F a c i l i t y	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Wanda Bill		Signature: <i>[Signature]</i>			Date: 6-10-21	

NON-HAZARDOUS WASTE MANIFEST

Generator's EPA ID No.

Profile No.

Page 1 of 1

PAWNEE WASTE LLC

Generator's Name and Mailing Address:

Tap Road

Manifest No.:

126358

Designated Facility Name and Site Address:

Pawnee Waste
47368 County Rd 118
Grover, CO 80729

Weld County USR No.:

USR15-0048

Facility Phone No.:

(970) 889-0006

Generator's Name and Mailing Address:

Well or Site Name:

HALE PAD

Truck/Haul Container

Total Quantity

Unit/Wt/Vol

AFER/Reference#:

No.:

Type:

LT11

JD

8829

TMS

Lat/Long:

Waste Name/Waste Type:

Port Soil

Special Handling Instructions:

Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste

Printed/Typed Name:

Signature:

Date:

Transporter Acknowledgement of Receipt of Materials

Transporter Company Name:

Lone Tree

US EPA ID No.:

Transporter's Phone No.: (include area code)

Printed/Typed Name:

LESTER THOMAS

Signature:

[Signature]

Date:

6-10-21

Discrepancy Indication Space:

Bill To Company Name: (if invoicing is other than the Generator Company listed above)

Lone Tree Services, LLC

Discrepancy Indication Space:

Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above

Printed/Typed Name:

Signature:

Date:

[Signature]

[Signature]

6-10-21

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE <small>LLC</small>	
Generator's Name and Mailing Address: Tap Root				Manifest No.: 126500		
Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006		
Generator's Name and Mailing Address: Tap Root	Well or Site Name: Hale Pad		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:		No.: LTS	Type: SD	2251	BUS
Lat/Long:						
Waste Name/Waste Type: Cont. Soil						
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Les Thomas		Signature: <i>Les Thomas</i>		Date: 6-10-21	
Disposal Facility	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Kendra Hill		Signature: <i>Kendra Hill</i>			Date: 6-10-21	

NON-HAZARDOUS WASTE MANIFEST

Generator's EPA ID No.

Profile No.

Page 1 of 1

PAWNEE WASTE LLC

Generator's Name and Mailing Address:
Tap Road

Manifest No.:

126359

Designated Facility Name and Site Address:
**Pawnee Waste
47368 County Rd 118
Grover, CO 80729**

Weld County USR No.:

USR15-0048

Facility Phone No.:

(970) 889-0006

Generator's Name and Mailing Address:
Designated Facility Name and Site Address:
Well or Site Name:
AFE#/
Lat/Long:
Waste Name/
Special Handling Instructions:
Generator's Certification:
Printed/Typed Name:
Signature:
Date:

Truck/Haul Container

Total Quantity

Unit/Wt/Vol

No.:

Type:

1502

TONS

Well or Site Name:
Tap Road

AFE#/
Cont. Soil

Special Handling Instructions:

Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste

Printed/Typed Name:

Signature:

Date:

Transporter Acknowledgement of Receipt of Materials

Transporter Company Name:

US EPA ID No.:

Transporter's Phone No.: (include area code)

Printed/Typed Name:

Signature:

Date:

Bill To Company Name: (if invoicing is other than the Generator Company listed above)

Lone Tree Services, LLC

Discrepancy Indication Space:

Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above

Printed/Typed Name:

Signature:

Date:

Kendrea Dull

6-10-21

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 126357		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006	
	Well or Site Name: Hale Pond			Truck/Haul Container		Total Quantity
	AFE#/Reference#:			No.: LTS	Type: SD	9030
	Lat/Long:			Unit/Wt/Vol: Tons		
Waste Name/Waste Type:	Cont Soil					
	Special Handling Instructions:					
	Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste					
	Printed/Typed Name:		Signature:		Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Les Thomas		Signature: Les Thomas		Date: 6.9.21	
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Discrepancy Indication Space:						
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Facility Owner or Operator:	Printed/Typed Name: Kendra Hill		Signature: Kendra Hill		Date: 6.9.21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE LLC	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 118819		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006	
	Well or Site Name: Hole Pad		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:		No.: Lone 119	Type: 30	8554	1025
	Lat/Long:		Waste Name/Waste Type: Cont. Soil			
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:			Signature:		Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services, LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Troy J. ...		Signature:		Date: 6-1-21	
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name:			Signature:		Date: 6-1-21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE	
Generator's Name and Mailing Address:				Manifest No.: 118018		
Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006		
Generator's Name and Mailing Address:	Well or Site Name: Auto Pad		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE# / Reference#:		No.:	Type:	5800	TONS
	Lat/Long:					
	Waste Name/Waste Type: Auto Pad					
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services, LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Tracy Quinn		Signature:			Date: 6-9-21
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Monter Hill		Signature:			Date: 6-9-21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE LLC	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 126356		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048	Facility Phone No.: (970) 889-0006		
	Well or Site Name: Hole Day		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:		No.:	Type:	2839	Tons
	Lat/Long:		LT5		50	
Waste Name/Waste Type: Cont. Soil						
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services, LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Les Thomas		Signature: Les Thomas			Date: 6-9-21
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Vandua Dil		Signature:			Date: 6-9-21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE <small>LLC</small>	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 126352		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006	
	Well or Site Name: Hole Day			Truck/Haul Container		Total Quantity
	AFE#/Reference#:			No.: LTS	Type: SD	241641
	Lat/Long:			Unit/Wt/Vol: TNS		
Waste Name/Waste Type: Contaminated soil						
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name: Les Thomas		Signature: <i>Les Thomas</i>			Date: 6-9-21	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name:		Signature:			Date: 6-9-21
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
	Printed/Typed Name: Kendra Dill		Signature: <i>Kendra Dill</i>			Date: 6-9-21

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE LLC	
Generator's Name and Mailing Address:	Tap Road			Manifest No.:		
				126161		
	Designated Facility Name and Site Address:		Weld County USR No.:	Facility Phone No.:		
	Pawnee Waste 47368 County Rd 118 Grover, CO 80729		USR15-0048	(970) 889-0006		
	Well or Site Name:		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
AFE#/Reference#:		No.:	Type:			
Lat/Long:		Lone Tree Services, LLC		SD	2583 TONS	
Waste Name/Waste Type:		Cent. Soil				
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Les Thomas		[Signature]			6.9.21	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name:		US EPA ID No.:	Transporter's Phone No.: (include area code)		
	Lone Tree Services, LLC					
	Printed/Typed Name:		Signature:			Date:
					6.9.21	
Disposal Facility	Bill To Company Name: (if invoicing is other than the Generator Company listed above)					
	Lone Tree Services, LLC					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name:		Signature:			Date:	
Kendra Hill		[Signature]			6.9.21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE LLC	
Generator's Name and Mailing Address:	Tap Room			Manifest No.: 126160		
	Designated Facility Name and Site Address:		Weld County USR No.:	Facility Phone No.:		
	Pawnee Waste 47368 County Rd 118 Grover, CO 80729		USR15-0048	(970) 889-0006		
	Well or Site Name:		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	Hole Pad		No.: Lone LT 19	Type: SD	24.26 20.15	tons
AFE#/Reference#:		Lat/Long:				
Waste Name/Waste Type:		Cull Soil				
Special Handling Instructions:		Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste				
Printed/Typed Name:		Signature:		Date:		
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name:		US EPA ID No.:	Transporter's Phone No.: (include area code)		
	Lone Tree Services, LLC					
	Printed/Typed Name:		Signature:		Date:	
Felipe Garcia				6-9-21		
Bill To Company Name: (if invoicing is other than the Generator Company listed above)	Lone Tree Services, LLC					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name:		Signature:		Date:		
Kendra Hill				6-9-21		

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE LLC	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 118876		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006	
	Well or Site Name: Hole Road		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:		No.:	Type:	2671	20
	Lat/Long:		Waste Name/Waste Type:			
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name:		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name:		Signature:		Date:	
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name:		Signature:			Date:	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE <small>LLC</small>	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 126355		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048	Facility Phone No.: (970) 889-0006		
	Well or Site Name: Hale Day		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:		No.:	Type:	26 35 TONS	
	Lat/Long:		LTS SD			
Waste Name/Waste Type: Cont Soil						
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services, LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Les Thomas		Signature: Les Thomas		Date: 6-9-21	
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Kendren Hill		Signature: Kendren Hill			Date: 6-9-21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE <small>LLC</small>	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 126334		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048	Facility Phone No.: (970) 889-0006		
	Well or Site Name: Hale Day		Truck/Haul Container		Total Quantity	Unit/Wt/Vol
	AFE#/Reference#:		No.: LTS	Type: SD	27.86	TONS
	Lat/Long:		Waste Name/Waste Type: Cont Soil			
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name: Eric Thomas		Signature: <i>Eric Thomas</i>			Date: 6-9-21	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services		US EPA ID No.:	Transporter's Phone No.: (include area code)		
	Printed/Typed Name: Eric Thomas		Signature: <i>Eric Thomas</i>		Date: 6-9-21	
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal Facility	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Kendra Hill		Signature: <i>Kendra Hill</i>			Date: 6-9-21	

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE	
Generator's Name and Mailing Address:	Tap Road			Manifest No.: 118817		
	Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048		Facility Phone No.: (970) 889-0006	
	Well or Site Name: Hole Pool			Truck/Haul Container		Total Quantity
	AFE#/Reference#:			No.:	Type:	Unit/Wt/Vol
	Lat/Long:			Waste Name/Waste Type: Coal Dust		
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
Transporter Acknowledgement of Receipt of Materials	Transporter Company Name: Lone Tree Services, LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)	
	Printed/Typed Name: Troy Miller		Signature:			Date: 11-5-21
	Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC					
Disposal	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
Printed/Typed Name: Kerwin Dill		Signature:			Date: 11-5-21	

Waste Pad

NON-HAZARDOUS WASTE MANIFEST		Generator's EPA ID No.	Profile No.	Page 1 of 1	PAWNEE WASTE <small>LLC</small>	
Generator's Name and Mailing Address: Tap Road 11 West out front trail 11 West 380910538			Manifest No.:		126162	
Designated Facility Name and Site Address: Pawnee Waste 47368 County Rd 118 Grover, CO 80729		Weld County USR No.: USR15-0048	Facility Phone No.: (970) 889-0006			
G e n e r a t o r	Well or Site Name: Hale Pad	Truck/Haul Container		Total Quantity	Unit/Wt/Vol	
	AFER/Reference#:	No.:	Type:			
	Lat/Long:	269	SD	2192	TONS	
	Waste Name/Waste Type: cont. soil					
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:			Date:	
T r a n s p o r t e r						
Transporter Acknowledgement of Receipt of Materials						
Transporter Company Name: Lone Tree Services, LLC		US EPA ID No.:		Transporter's Phone No.: (include area code)		
Printed/Typed Name: Felipe Garcia		Signature:			Date: 6-9-21	
D i s p o s a l						
Bill To Company Name: (if invoicing is other than the Generator Company listed above) Lone Tree Services, LLC						
Discrepancy Indication Space:						
Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)						
F a c i l i t y						
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above						
Printed/Typed Name: Kendra Bill		Signature:			Date: 6-9-21	