

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402805022

Date Received:  
09/08/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766  
Name of Operator: ARKOMA OPERATIONS LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Andrew Price</u>	<u>318-965-0044</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903478  
Inspection Date: 07/27/2021 FIR Submit Date: 07/28/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1001 17TH STREET STE 1160  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311916

Location Name: IGW Number: N33N8W 6SESW County: LA PLATA  
Qtrqtr: SESW Sec: 6 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.128830 Longitude: -107.763370

FACILITY - API Number: 05-067-00 Facility ID: 288622

Facility Name: IGW Number: 124  
Qtrqtr: SESW Sec: 6 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.128830 Longitude: -107.763370

CORRECTIVE ACTIONS:

1 CA# 154323

Corrective Action: -Spot seeding needs to be conducted along pipeline right of way, where bare soils are not stabilized with perennial vegetation. Seed mix needs to be comprised of seed species representative of the native dominated, surrounding reference area.

Date: 11/01/2021

Response: CA COMPLETED Date of Completion: 09/07/2021

Operator Comment: Installed diversion ditches across the pipe line ROW to prevent storm water erosion. The surface of the exposed soil was roughened and re-seeded.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 154324

Corrective Action: -Stormwater BMPs and erosion controls need to be installed to stabilize erosion within the project area. Corrective action is back-dated to original corrective action date (7/15/2020) as corrective action is not adequately addressed and active erosion is observed.

Date: 07/15/2020

Response: CA COMPLETED

Date of Completion: 09/07/2021

Operator Comment: Cleared drainage ditches of sediment and reinforced the berms on the North and East sides of the location. Reseeded and installed erosion blankets on the berms and slopes on the North side of the location.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 9/8/2021 12:54:47 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402805038	IGE 123B, 124, 125 9-8-2021 corrective actions

Total Attach: 1 Files