

Waag South SESW Pad 1 (439204) – Supplemental Photo Log



Photos Taken 8/31/2021 – Showing external corrosion hole point of failure.



Photo Taken 8/31/2021 – Photo taken following replacement of compromised section of flowline.