

Caerus Piceance LLC
F24X-32G
Location # 316369



Location/lack of battery signage



location

Caerus Piceance LLC
F24X-32G
Location # 316369



location



location

Caerus Piceance LLC
F24X-32G
Location # 316369



Lack of stabilization/compaction



Sediment migration from pad next to separator

Caerus Piceance LLC
F24X-32G
Location # 316369



Lack of stabilization/compaction



Lack of stabilization/compaction