



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment inside wellhead fencing. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 08/17/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	iron		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 294775 Type: WELL API Number: 123-25553 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSEPTION DOC#: 679604079.</b>                      All previous corrective actions assigned to this location have not been resolved. All previous corrective actions have been re-assigned to this location with its original corrective action date. No new corrective actions were observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary                      **Weather Conditions: sunny, dry ground                      On Monday, September 13, 2021 at approximately 13:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at ANDREWS 34-34 (PDC Energy), at API #: 05-123-25553 in WELD Colorado.                      While there, I observed a shut in wellhead.                      During this inspection the following possible compliance issues were observed:                      1. Unused/disconnected equipment is inside wellhead fencing. Reconnect equipment or remove from location to comply with Rule 606. (Corrective Action Date: August 17, 2021)                      See attached photos #2, 3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	09/14/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604145	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5530289">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5530289</a>