

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402811988

Date Received:

09/15/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

Jones, Tammy

tajones@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903354

Inspection Date: 07/02/2021

FIR Submit Date: 07/06/2021

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326226

Location Name: HUBER-LEWIS-N34N8W Number: 4NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 4 Twp: 34N Range: 8W Meridian: N

Latitude: 37.241040 Longitude: -107.746630

FACILITY - API Number: 05-067-00 Facility ID: 216068

Facility Name: HUBER-LEWIS Number: 2-4

Qtrqtr: NWSE Sec: 4 Twp: 34N Range: 8W Meridian: N

Latitude: 37.241040 Longitude: -107.746630

CORRECTIVE ACTIONS:

1 CA# 152434

Corrective Action: -Revegetation needs to be conducted within the southern project area. Corrective action is back-dated to 4/1/2020 to document duration of non-compliance as corrective action is not addressed. Soil remediation may be needed. Livestock exclusion may be needed.

Date: 04/01/2020

Response: CA COMPLETED

Date of Completion: 09/13/2021

Operator
Comment:

Attached are pictures of the seeding and mulching that was completed on the subject well's location.

COGCC Decision: _____

COGCC
Representative:

2 CA# 152435

Corrective Action: -Install stormwater (ie: BMPs) and erosion controls (ie: mulch, ebiodegradable erosion blanket, etc.). Controls need to be selected, sized, installed, and maintained according to good engineering practices. Corrective action is back-dated to 1/10/2020 to document duration of non-compliance as stormwater erosion remains uncontrolled within the project area.

Date: 01/10/2020

Response: CA COMPLETED

Date of Completion: 09/13/2021

Operator
Comment:

Attached are pictures of the seeding and mulching that was completed on the subject well's location.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 9/15/2021 9:39:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402811991	Huber-Lewis 2-4 Resolved Photos
-----------	---------------------------------

Total Attach: 1 Files