

NEW ELK 25-16 API# 05-071-09237 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 15, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104822



PHOTO 1: MAINTENANCE WAS CONDUCTED TO THE LIQUID RING COMPRESSOR TO STOP THE OIL LEAK. THE IMPACTED SOIL/GRAVEL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION. SELF INSPECTION PROCESS WAS REVIEWED.