



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Some automation equipment			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Exposed to surface			
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 276135 Type: WELL API Number: 001-09533 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: All tubing has been removed except one joint used to install wellhead wraparound equipment.

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/18/2020 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Bradenhead inaccessible or not visible Date: 09/26/2021

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On 9/16/21 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Abbott 10-43                      Company Name- P3                      API- 05-001-09533                      In Adams County Colorado.                      While there, I observed TA well                      During this inspection the following possible compliance issues were observed:                      Bradenhead inaccessible or not visible                      Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)                      9/26/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      Previous inspection corrective actions may still be valid.                      This is a summary of inspection report.</p>	<p>medinaj</p>	<p>09/16/2021</p>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503175	Inspection Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533929">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533929</a>