

FORM  
6Rev  
11/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

402736346

Date Received:

07/01/2021

### WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: CANDICE BARBER

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Phone: (307) 233-4513

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: CANDICE\_BARBER@OXY.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-10722-00

Well Name: FORT ST VRAIN

Well Number: 14

Location: QtrQtr: SWSE Section: 11 Township: 3N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

### Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.235970

Longitude: -104.854963

GPS Data: GPS Quality Value: 1.5 Type of GPS Quality Value: PDOP Date of Measurement: 06/21/2021

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

### Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7158	7168	03/19/2021	B PLUG CEMENT TOP	7080
J SAND	7586	7636	03/19/2021	B PLUG CEMENT TOP	7515
DAKOTA	7743	7838	03/19/2021	B PLUG CEMENT TOP	7675

Total: 3 zone(s)

### Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	521	500	521	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	7741	280	7741	5900	CBL

### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7675 with 2 sacks cmt on top. CIBP #2: Depth 7515 with 2 sacks cmt on top.

CIBP #3: Depth 7080 with 2 sacks cmt on top. CIBP #4: Depth 6810 with 2 sacks cmt on top.

CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 130 sks cmt from 2500 ft. to 2200 ft.

Plug Type: CASING

Plug Tagged: ☐

Set 110 sks cmt from 1500 ft. to 1280 ft.

Plug Type: OPEN HOLE

Plug Tagged: ☒

Set 120 sks cmt from 1280 ft. to 1078 ft.

Plug Type: OPEN HOLE

Plug Tagged: ☒

Set 150 sks cmt from 1078 ft. to 808 ft.

Plug Type: OPEN HOLE

Plug Tagged: ☒

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Plug Type: \_\_\_\_\_

Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing

CICR Depth \_\_\_\_\_

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing

CICR Depth \_\_\_\_\_

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing

CICR Depth \_\_\_\_\_

(Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 625 ft. to 379 ft.

Plug Tagged: ☒

Set 48 sacks at surface

Cut four feet below ground level, weld on plate

Above Ground Dry-Hole Marker: ☐ Yes

☒ No

Set \_\_\_\_\_ sacks in rat hole

Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1500 ft. of 4+1/2 inch casing

Number of Days from Setting Surface Plug to Capping or Sealing the Well: 84

Surface Plug Setting Date: 03/29/2021 Cut and Cap Date: 06/21/2021

\*Wireline Contractor: RELIANCE

\*Cementing Contractor: SCHLUMBERGER

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes

☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: CANDICE BARBER

Title: REGULATORY ANALYST

Date: 7/1/2021

Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric

Date: 9/20/2021

CONDITIONS OF APPROVAL, IF ANY:

### Condition of Approval

#### COA Type

#### Description

0 COA

### Attachment List

#### Att Doc Num

#### Name

402736346	FORM 6 SUBSEQUENT SUBMITTED
402736388	OPERATIONS SUMMARY
402736389	CEMENT BOND LOG
402736392	CEMENT JOB SUMMARY
402736393	WELLBORE DIAGRAM
402736394	WIRELINE JOB SUMMARY
402736395	OTHER

Total Attach: 7 Files

### General Comments

#### User Group

#### Comment

#### Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)