

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2021

Submitted Date:

09/22/2021

Document Number:

696303628

FIELD INSPECTION FORM

Loc ID 457131 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10661
Name of Operator: BISON OIL & GAS II LLC
Address: 518 17TH STREET #1800
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------|
| | | ops@bisonog.com | |
| Kraich, Adam | | adam.kraich@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 457132 | WELL | PR | 02/22/2019 | OW | 123-47779 | Hunt 8-60 17A-8-2 | PR |

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-----------------|-------|--|
| Type | DRILLING/RECOMP | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|------------|
| Comment: | Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos Location is over 2.5 Miles in from a Public Road. No Directional Sign Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.) | Date: | 09/24/2021 |
| Corrective Action: | Install sign to comply with Rule 605.c.(1)-(3) Flowback/Completion directional sign not posted. Workover Rig Sign not posted at Entrance from a Public Road | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 457132 Type: WELL API Number: 123-47779 Status: PR Insp. Status: PR**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday 09/22/2021 at approximately 16:20, I, Inspector Erica Petrie, conducted a Field Inspection at Bison Oil and Gas II, Hunt 8-60 17A PAD Location #457131 in Weld County, Colorado.</p> <p>While there, I observed Completion Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Workover Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos Location is over 2.5 Miles in from a Public Road. No Directional Signs Provided. (Main Lease Road has Multiple Leases, from Multiple Operators.) Install signs to comply with Rule 605.c. (1)-(3) Flowback/Completion Directional Signs not posted. Corrective Action date 09.24.2021</p> | petrie | 09/22/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696303629 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538069 |