

GOLDEN EAGLE 32-10 API# 05-071-08651 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104828



PHOTO 1: THE COMPRESSOR ENGINE WAS SCHEDULED FOR AN ENGINE SWAP ON 09/17/21, WHICH WAS COMPLETED.

GOLDEN EAGLE 32-10 API# 05-071-08651 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 16, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104828



PHOTO 2: THE FLUID IN THE CONTAINMENT OF THE LIQUID RING PRIMARILY CONSISTED OF RAIN WATER FROM THE STORM ON TUESDAY NIGHT 9/14/21. THIS FLUID WAS REMOVED ON 09/16/21.

GOLDEN EAGLE 32-10 API# 05-071-08651 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 20, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104828



PHOTO 3: MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING WAS CLEANED UP AND REMOVED FROM LOCATION AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

GOLDEN EAGLE 32-10 API# 05-071-08651 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 20, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104828



PHOTO 4: MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING WAS CLEANED UP AND REMOVED FROM LOCATION AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.