

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402825207

Date Received:

09/28/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

Arthur, Denise

denise.arthur@state.co.us

Labowskie, Steve

steve.labowskie@state.co.us

Hughes, Jim

jimo.hughes@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903489

Inspection Date: 07/29/2021

FIR Submit Date: 07/30/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 312051

Location Name: BONDAD 33-9-N33N9W Number: 2SESW County: LA PLATA

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129012 Longitude: -107.799810

FACILITY - API Number: 05-067-00 Facility ID: 263927

Facility Name: BARNES A Number: 2

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129012 Longitude: -107.799810

CORRECTIVE ACTIONS:

1 CA# 154367

Corrective Action: -Per Rule 421.b. for wells within the 100 year floodplane submit as an attachment to a Form 4, Operator's Flood Shut-In Plan by 8/2/2021.

Date: 08/02/2021

Response: CA COMPLETED

Date of Completion: 09/28/2021

Operator Comment: The Stormwater Plan is submitted per the Field Inspection Form Document Number 693903489. The report states "Per Pule 421.b. for wells within the 100 year floodplane submit as an attachment to a Form 4, Operator's flood Shut-in Plan." The report also discussed a significant stormwater event on the Barnes A2 well pad. Per an email from Missti Mason requesting help submitting the Floodplain Shut-In Plan she said that we must maintain a Floodplain Shut-in but it is not submitted on a form. The SWMP is submitted on a Form 4. Because the inspection was re:SWMP, the SWMP is attached." to the form 4 - see Attached

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

2 CA# 154368

Corrective Action: -Remove and properly manage gravel, rock, and material displaced and discharged downslope of the well pad. Remove and properly dispose of debris deposited on well pad and around facilities. Submit (as an attachment to a Form 4) and implement a plan to properly divert and protect the location from degradation during significant stormwater events on the well pad using good engineering practices. All inlets and outlets need to be properly designed and constructed to ensure stabilization. Corrective action date is the day of the inspection (7/29/2021) as it is required that the corrective action be addressed immediately.

Date: 07/29/2021

Response: CA COMPLETED

Date of Completion: 08/18/2021

Operator Comment: see attached plan. Work has been completed

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed: \_\_\_\_\_

Title: admin asst

Date: 9/28/2021 1:57:41 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402825319	Approved Sundry
402825329	work completed
402825367	plan

Total Attach: 3 Files