

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402802718

Date Received:
09/29/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10736
Name of Operator: ADVANCED WIRELESS COMMUNICATIONS LLC
Address: 5500 RAIL RD
City: FARMINGTON State: NM Zip: 87402
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Krysten Moore</u>	<u>5054860045</u>	<u>krysten@advancedwirelessllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903525
Inspection Date: 08/06/2021 FIR Submit Date: 08/11/2021 FIR Status: _____

Inspected Operator Information:

Company Name: ADVANCED WIRELESS COMMUNICATIONS LLC Company Number: 10736
Address: 5500 RAIL RD
City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 306981

Location Name: SLUGGER-N33N8W Number: 18NWSE County: LA PLATA
Qtrqr: NWSE Sec: 18 Twp: 33N Range: 8W Meridian: N
Latitude: 37.101870 Longitude: -107.756610

FACILITY - API Number: 05-067-00 Facility ID: 289332

Facility Name: SLUGGER Number: 2
Qtrqr: NWSE Sec: 18 Twp: 33N Range: 8W Meridian: N
Latitude: 37.101870 Longitude: -107.756610

CORRECTIVE ACTIONS:

1 CA# 154776

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. by 9/13/2021. Berms need to be stabilized to prevent erosion.

Date: 09/13/2021

Response: CA COMPLETED Date of Completion: 09/24/2021

Operator Comment: Sediment that had fallen down into berm was pulled out and used to rebuild the containment area.

COGCC Decision: _____

COGCC
Representative:

2 CA# 154777

Corrective Action: -As numerous untreated Russian knapweeds were observed, corrective action to control weeds by 7/31/2021 is not adequately addressed. Therefore corrective action to control weeds needs to be immediately addressed.

Date: 07/31/2021

Response: CA COMPLETED

Date of Completion: 08/17/2021

Operator Comment: Flowing knapweeds had been removed on 7/12/21 and 7/13/21. After follow up inspection it was found that more had grown up and a few were missed on first removal effort. Sent crew back 8/17/21 to removed remaining knapweeds. Also around 8/13/21, Arkoma had their operator spot spray for the knapweed as well.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: We have instructed our operators to remove an thistles that may emerge in the future so that we can stay ahead of the flowering and spreading/outbreak of these invasive weeds.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: krysten Moore

Signed:

Title: vP

Date: 9/29/2021 11:34:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files