

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2021

Submitted Date:

09/29/2021

Document Number:

690202109

FIELD INSPECTION FORM

Loc ID 309122 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------|---------|
| Fitzgerald, Edie | | efitzgerald@ogrisop.com | |
| ATWATER BONNIE | | batwater@ogrisop.com | |
| Mack, Ronnie | | rmack@ogrisop.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 288299 | WELL | PR | 05/09/2008 | GW | 071-09111 | GOLDEN EAGLE 29-16 | RI |

General Comment:

This is a follow up of the previous inspection number 690201906.
The previous corrective actions have not been completed.
See attached photos and additional details within this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| Spills: | | | | | |
|---|----------|--------|--|-------------------------|--|
| Type | Area | Volume | | | |
| Produced Water | WELLHEAD | | | | |
| Comment: There is a dripping water leak at the wellhead that needs to be repaired. Previous corrective action was not completed. Corrective action needs to be performed immediately. | | | | | |
| Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. | | | | Date: <u>08/05/2021</u> | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----------------------|-------|--|
| Yes/No | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|----------------------|-------|
| Type | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: There is erosion along the access road traveling to the location. The cattleguard is not maintained and is filled in with sediment. There is erosion along the side of the road which needs BMPs to prevent further erosion. Previous corrective action was not completed. Corrective action needs to be performed immediately to obtain compliance.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

Pits: NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 292686 | 2059199 | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 690202110 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543288 |