

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2021

Submitted Date:

09/29/2021

Document Number:

690202111

**FIELD INSPECTION FORM**Loc ID 309141 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ATWATER BONNIE		batwater@ogrisop.com	
Mack, Ronnie		rmack@ogrisop.com	
Fitzgerald, Edie		efitzgerald@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288584	WELL	PR	12/27/2006	GW	071-09140	GOLDEN EAGLE 32-4	RI

**General Comment:**

This is a follow up of the previous inspection number 690201908.  
The previous corrective actions have not been completed.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment:

There are noxious along areas of the road and at the edge of the well pad. Previous corrective action was not performed.

Corrective Action:

Comply with Rule 1003.f.

Date: 09/15/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Did not observe the leak at wellhead.



Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the side of the road which needs to be repaired and stabilized. Previous corrective action was not completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	293758	2059558	
	293758	2059558	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202112	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543289">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543289</a>