

**FORM**  
**5**Rev  
02/20**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402278801

Date Received:

09/29/2021

**DRILLING COMPLETION REPORT**

Per Rule 308A, this form and all required attachments shall be submitted after completing the drilling operations to drill, sidetrack, or deepen a wellbore and after changing the casing and/or cement configuration of a wellbore. If any attempt has been made to test, complete, or produce the well, the operator shall also submit a Form 5A (Completed Interval Report) per Rule 308B. If the well has been plugged, the operator shall also submit a Form 6 (Well Abandonment Report) per Rule 311.

Completion Type ☒ Final completion ☐ Preliminary completion

OGCC Operator Number: 10071

Contact Name: Kate Miller

Name of Operator: HIGHPOINT OPERATING CORPORATION

Phone: (720) 440-6116

Address: 555 17TH ST STE 3700

Fax:

City: DENVER

State: CO

Zip: 80202

Email: regulatory@bonanzacrk.com

API Number 05-123-49720-00

County: WELD

Well Name: Grinde

Well Number: 01-64-05-6457CB

Location: QtrQtr: NWSW Section: 5 Township: 1N Range: 64W Meridian: 6  
FNL/FSL FEL/FWL

Footage at surface: Distance: 1550 feet Direction: FSL Distance: 365 feet Direction: FWL

As Drilled Latitude: 40.077500 As Drilled Longitude: -104.582950

GPS Data: GPS Quality Value: 1.5 Type of GPS Quality Value: PDOP Date of Measurement: 10/23/2019

GPS Instrument Operator's Name: Scott Estabrooks

FNL/FSL

FEL/FWL

\*\* If directional footage at Top of Prod. Zone Dist: 14 feet Direction: FSL Dist: 504 feet Direction: FWL  
Sec: 5 Twp: 1N Rng: 64W

FNL/FSL

FEL/FWL

\*\* If directional footage at Bottom Hole Dist: 0 feet Direction: FSL Dist: 401 feet Direction: FEL  
Sec: 4 Twp: 1N Rng: 64W

Field Name: WATTENBERG

Field Number: 90750

Federal, Indian or State Lease Number:

Spud Date: (when the 1st bit hit the dirt) 10/30/2019 Date TD: 12/05/2019 Date Casing Set or D&amp;A: 12/07/2019

Rig Release Date: 12/24/2019 Per Rule 308A.b.

Well Classification:

☐ Dry ☒ Oil ☐ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

Total Depth MD 17390 TVD\*\* 7007 Plug Back Total Depth MD 17373 TVD\*\* 7008

Elevations GR 5030 KB 5047

Digital Copies of ALL Logs must be Attached per Rule 308A ☒

List Electric Logs Run:

MWD/LWD, CBL, [RES in 05-123-49721]

**CASING, LINER AND CEMENT**

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	20	16	84	0	97	78	0	97	VISU
SURF	13+1/2	9+5/8	36	0	1,259	350	0	1,259	VISU
1ST	8+3/4	7	23	0	7,693	365	3,432	7,693	CALC
1ST LINER	6+1/8	4+1/2	13.5/11.6	0	17,387	700	3,022	17,387	CBL

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analysis must be submitted to COGCC)
	Top	Bottom	DST	Cored	
PARKMAN	4,377		NO	NO	
SUSSEX	4,949		NO	NO	
SHANNON	5,530		NO	NO	
SHARON SPRINGS	6,974		NO	NO	
NIOBRARA	7,347		NO	NO	

Operator Comments:

- PBTD is taken from the wet shoe sub.
- The TPZ is actual.
- The BHL location was drilled past the 460' setback, however the actual BPZ is reported on the Form 5A.
- Alternative Logging Program: No open-hole logs were ran on this well. A Resistivity log was ran on Grinde 01-64-05-4841B (API# 05-123-49721). Approved APD had BMP requiring one well on pad to be logged with open hole resistivity log with gamma ray.
- As-Drilled GPS data was taken when conductor was set.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst Date: 9/29/2021 Email: regulatory@bonanzaark.com

### Attachment Check List

Att Doc Num	Document Name	attached ?			
<u>Attachment Checklist</u>					
402307627	CMT Summary *	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Core Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
402307576	Directional Survey **	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	DST Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Logs	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Other	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
<u>Other Attachments</u>					
402307618	DIRECTIONAL DATA	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
402307637	PDF-CEMENT BOND	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
402307638	PDF-MWD/LWD	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
402307639	LAS-MWD/LWD	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
402811190	LAS-CEMENT BOND	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
402816912	PDF-MWD/LWD	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	TPZ may need corrected - Top perforation at 7625' reported on the 5A appears to be illegal	01/07/2021

Total: 1 comment(s)