

Inspection Photos
Location Name: Rocky Mountain Fuel C-10
Location ID: 323229



Pic 1 pump jack



Pic 2 stained soil near pump jack motor/mechanical issue