

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/27/2021

Submitted Date:

09/27/2021

Document Number:

699503208

FIELD INSPECTION FORM
 Loc ID 333050 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257528	WELL	PR	12/06/2000	OW	123-19989	ROCKY MOUNTAIN FUEL CO 9-8	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Stained soil/mechanical issue with gas motor. Stained soil needs to be removed.
Mechanical issues need to be addressed.

Corrective Action:

Comply with COGCC housekeeping rules

Date: 10/27/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Prime Mover

1

Comment:

Gas motor

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Plumbed to surface

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 257528 Type: WELL API Number: 123-19989 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 07/29/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 9/27/21 at approximately 1445 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Rocky Mountain Fuel Co 9-B</p> <p>Company Name- KPK</p> <p>API- 05-123-19989</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil/mechanical issue with gas motor. Stained soil needs to be removed.</p> <p>Mechanical issues need to be addressed.</p> <p>Comply with COGCC housekeeping rules 10/27/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	09/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503209	Inspection Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545987