

TEP
RGU 44-1
Location # 335640



Location/ lack of battery signage



location

TEP
RGU 44-1
Location # 335640



location



Lack of labeling on glycol vessels

TEP
RGU 44-1
Location # 335640



Glycol vessel dimensions



Glycol vessel dimensions

TEP
RGU 44-1
Location # 335640



Glycol vessel dimensions



Tank burner missing cap/access for wildlife

TEP
RGU 44-1
Location # 335640



Lack of stabilization/erosion



Erosion on access road



Well head signs are illegible