



**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Frac		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Sound Wall		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 457362 Type: LOCATION API Number: - Status: AC Insp. Status: AO

**Complaint**

Comment: Inspection in response to complaint.  
 Field Inspector Assigned: Adam Burns  
 Complaint Received  
 Date: 10-5-2021  
 Complaint Contacted: Yes via phone  
 Date: 10-7-2021 Time: 14:28PM  
 Location ID # 457326  
 Location name: Knight Pad  
 Inspection Document # 699104561  
 Complaint inspection document #699104579  
 Complaint Document #402832561  
 Nature of Complaint: Noise/ Vibration  
 Field Inspector Actions:  
 On 10-7-2021, I Adam Burns area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Kathy Kemper at 524 Nesting Crane Lane stated the issues were occurring outside of complainants home.  
 On 10-7-2021, I attempted to make contact with the complainant who indicated that on 10-5-2021 experiencing noise and vibration at the residence.  
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise in or around location. I did not observe any changes in equipment on site. I performed a sound study, which is attached to complaint inspection. It appears to be over 65 db(C).  
 At time of inspection, I spoke with Nextier Completion Solutions Frac supervisor he stated at time of complaint they were Fracking and no unusual activity was taking place and no change of equipment. They tentatively plan, on being done in a week if no issues occur.  
 All information reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action: **Suggest a mitigation plan for noise/vibration per rule 423**

Date: 10/12/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104580	Sound Audit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551202">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551202</a>
699104581	Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551203">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551203</a>
699104582	Sound Meter Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551204">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551204</a>