

Inspection Photos

API: 071-08113

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 1. Facing northeast along the main road near the electric gate. Stormwater is directed down the road side in this area which is contributing to erosion further down the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 2. This culvert along the main road is partially washed out and needs to be repaired. There is an exposed pipeline shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 3. The same culvert inlet is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 4. There is erosion along the side of the road which has exposed a pipe line shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 5. Further west along the access road there is erosion along the road. BMP's need to be installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 6. Facing back east along the access road. Areas of erosion have not been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 7. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021

Inspection Photos



Photo 8. Facing toward the pit. Water level has been lowered. The pit is shallow >2 ft. deep and needs to be constructed to allow 2 ft. freeboard. Earthen berms should be installed around the pit for containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 10/12/2021