

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402841784

Date Received:

10/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Huntington, Heather

hhuntington@enduringresources.com

Walter, Kyle

kwalter@enduringresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903639

Inspection Date: 09/09/2021

FIR Submit Date: 09/10/2021

FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 326208

Location Name: INDIAN CREEK WHEELER- Number: 13SENW County: LA PLATA
M34N10W

Qtrqtr: SENW Sec: 13 Twp: 34N Range: 10W Meridian: M

Latitude: 37.193352 Longitude: -107.885371

FACILITY - API Number: 05-067- -00 Facility ID: 216044

Facility Name: INDIAN CREEK WHEELER Number: 13-2

Qtrqtr: SENW Sec: 13 Twp: 34N Range: 10W Meridian: M

Latitude: 37.193352 Longitude: -107.885371

CORRECTIVE ACTIONS:

1 CA# 155770

Corrective Action: -Stormwater and erosion controls need to be installed to stabilize erosion on the well pad and access road. Stormwater and erosion controls need to be selected, sized, installed, and maintained according to good engineering practices that will ensure long-term stabilization such as those described by CDOT in their erosion control manuals. Erosion controls such as mulch, straw blanket etc. need to be installed and maintained until eroding areas are stabilized with desirable perennial vegetation. Response to 2020 corrective action to address stormwater erosion on the access road is inadequate. Corrective action date: 10/10/2021.

Date: 10/10/2021

Response: CA COMPLETED

Date of Completion: 10/04/2021

Operator
Comment:

CORRECTIVE ACTION WAS COMPLETED PLEASE SEE ATTACHED PHOTOS

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HEATHER HUNTINGTON

Signed:

Title: PERMITTING TECH

Date: 10/14/2021 9:16:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402841797	CA PHOTOS
-----------	-----------

Total Attach: 1 Files