

TEP
GGU 6-31
Location # 334881



Oct 12, 2021 at 10:55:35 AM
+39.485061,-107.599909 ±4.75m
COGCC

location



Oct 12, 2021 at 10:55:43 AM
+39.485061,-107.599909 ±4.75m
COGCC

location

TEP
GGU 6-31
Location # 334881



Location/unused ECD



location



TEP
GGU 6-31
Location # 334881



Bull plug/cap missing on load out line



Cut slope lack of stabilization/erosion/riling

TEP
GGU 6-31
Location # 334881



Cut slope lack of stabilization/erosion/riling



Cut slope lack of stabilization/erosion/riling



TEP
GGU 6-31
Location # 334881



Fill slope erosion/sediment migration



Fill slope erosion/sediment migration

