

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2021

Submitted Date:

10/25/2021

Document Number:

689501316

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Ray Gorka		RGorka@kpk.com	KPK
Graber, Nikki		nikki.graber@state.co.us	
Jeff Rickard		JRickard@kpk.com	KPK
Canfield, Chris		chris.canfield@state.co.us	

General Comment:

This is an environmental inspection of stained soil observed along access road to Spill ID 478542 only. Any corrective actions from previous inspections of Spill ID 478542 (Cosslet A 9 Flowline Spill) are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photo attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Surface stained soil was observed at two locations adjacent to the header and along flowline path off of the access road to the Cosslet A 9 Flowline spill (Spill ID 478542/ Rem No. 18952), approximately 300' southwest of the spill excavation area. See inspection photos.

Corrective Action: Properly dispose of oily waste in accordance with 905.e. Operator will investigate to determine the source of the stained soil and submit a Form 19 if reportable under Rule 912.b. If the spill is not reportable Operator will submit documentation, including root cause and photographs, as a FIRR.

Date: 10/25/2021

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment

User

Date

Operator emailed 10/22/2021 to provide notice of stained soil and upcoming corrective actions.

oakmank

10/25/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501317	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5562963