

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402786818

Date Received:

08/31/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Andrew Price

918-965-0044

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903529

Inspection Date: 08/06/2021

FIR Submit Date: 08/12/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325129

Location Name: HERRERA UNIT B-N33N8W Number: 20NWNW County: LA PLATA

Qtrqr: NWN Sec: 20 Twp: 33N Range: 8W Meridian: N  
W

Latitude: 37.093730 Longitude: -107.745630

FACILITY - API Number: 05-067- -00 Facility ID: 214078

Facility Name: HERRERA UNIT B Number: 1

Qtrqr: NWN Sec: 20 Twp: 33N Range: 8W Meridian: N  
W

Latitude: 37.093730 Longitude: -107.745630

CORRECTIVE ACTIONS:

1 ☒ CA# 154779

Corrective Action: -Repair or install berms or other secondary containment devices per Rule 603.o. by 9/11/2021. Berms need to be stabilized to prevent erosion.

Date: 09/11/2021

Response: CA COMPLETED

Date of Completion: 08/30/2021

Operator Comment: Rebuilt tank containment berms.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 154780

Corrective Action: -Stormwater (ie: BMPs) and erosion controls (ie: erosion control blanket, hydromulch, etc.) need to be installed to stabilize erosion and prevent sediment discharge within the project area, no later than 8/30/2021. Controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 08/30/2021

Response: CA COMPLETED

Date of Completion: 08/30/2021

Operator Comment: Dug diversion ditches on ROW to divert storm water to a natural drainage, cleaned the silt out of diversion ditches and built a silt pond on the edge of the location. Installed rock check dams along the diversion ditches and downstream from culvert outlet. Re-seeded the berms and bare slopes.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: 1.Rebuilt tank containment berms.  
2.Dug diversion ditches on ROW to divert storm water to a natural drainage, cleaned the silt out of diversion ditches and built a silt pond on the edge of the location. Installed rock check dams along the diversion ditches and downstream from culvert outlet. Re-seeded the berms and bare slopes.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 8/31/2021 3:54:22 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402786818	FIR RESOLUTION SUBMITTED
402798212	Herrera Unit B1 Corrective Action

Total Attach: 2 Files