

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2021

Submitted Date:

10/15/2021

Document Number:

700900794**FIELD INSPECTION FORM**Loc ID 319973 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access roads not accessible or maintained to get to well.		
Corrective Action	Location is within a designated setback location, maintain and repair access roads per Rule 204. Corrective Action Date 11/12/2021. See attached photo #1.	Date:	11/12/2021

Overall Good: ☐

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday September 30, 2021. at approximately 12:00pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Simpson A12, Fritzler Oil, at API #001-07472 in Adams County Colorado. While there, I observed a producing well. During this inspection the following possible compliance issues were observed: Access roads not accessible or maintained to get to well. Location is within a designated setback location, maintain and repair access roads per Rule 204. Corrective Action Date 30 days. See attached photo #1. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	10/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900796	Inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5565037