

APACHE CANYON 18-09 API# 05-071-06339 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 25, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201815



PHOTO 1: THE CONTRACTOR FROM A SEPARATE PROJECT DISTURBED THE VEGETATION BY LEAVING THE BLADE DOWN WHILE CROSSING THE ROAD. THE DISTURBANCE WAS RECLAIMED AND SEEDING WITH AN APPROVED CPW SEED MIX ON 10/25/2021.

APACHE CANYON 18-09 API# 05-071-06339 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 28, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201815



PHOTO 2: THE CULVERT OUTLET ON THE MAIN LEASE ROAD OF BIG BINGHAM CANYON AND THE RIDGE ROAD INTERSECTION WAS BELOW GRADE AND WOULD NOT DRAIN PROPERLY. POSITIVE DRAINAGE WAS ESTABLISHED FOR THE OUTLET. THE DISTURBED SOIL WAS SEEDED WITH AN APPROVED CPW SEED MIX TO ESTABLISH VEGETATION. EROSION CONTROL BLANKETS WERE INSTALLED FOR TEMPORARY SOIL STABILIZATION.

APACHE CANYON 18-09 API# 05-071-06339 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 28, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201815



PHOTO 3: THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO IMPROVE STABILIZATION EFFORTS.

APACHE CANYON 18-09 API# 05-071-06339 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 28, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201815



PHOTO 4: THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO IMPROVE STABILIZATION EFFORTS.