

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2021

Submitted Date:

11/02/2021

Document Number:

696203324

**FIELD INSPECTION FORM**Loc ID 453726 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10163

Name of Operator: NONSUCH NATURAL GAS INC

Address: P O BOX 110066

City: NAPLES State: FL Zip: 34108

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lee, David	239-289-9046	dlee@nng.us.com	
Arthur, Denise		denise.arthur@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453726	LOCATION	AC			-	CSOC TB Location	RI

**General Comment:**

On 11/1/2021, Reclamation Specialist Trujillo inspected Nonsuch Natural Gas Inc's CSOC TB Location in Garfield County, Colorado.

This inspection is a followup to:

#696201797 dated 9/16/2020;

#696201822 dated 9/24/2020;

#696201988 dated 11/02/2020;

#696202916 dated 7/12/2021;

and #696203087 dated 8/23/2021 to document compliance with the following corrective actions:

606: Unused or unneeded equipment on the Location

606: Good Housekeeping

1002.f: Stormwater

1200: Wildlife Protection measures

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

Refer to the "Good Housekeeping" Equipment", "Reclamation", "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Previous inspections documented unused pipe equipment stored behind the methanol tank. Inspections required Operator to comply with Rule 603.f (now Rule 606).</p> <p>It was observed in this inspection that the various unused pipe remains improperly stored on the Location, behind the methanol tank.</p> <p>This corrective action has not been addressed and remains applicable.</p>		
Corrective Action:	Comply with Rule 606 and remove unused equipment.	Date:	11/10/2020
Type	UNUSED EQUIPMENT		
Comment:	<p>Previous inspections documented equipment on the Location (200 bbl tank, 500 gallon methanol tank, separator) that did not appear to be active, or necessary for production activities on the Location.</p> <p>Operator was required to submit a Form 4 sundry with records identifying equipment's current status and use for production on the Location by 10/2/2020. Inspection #696203087 noted that Operator failed to submit the documentation and required Operator to comply with Rule 606.a and remove unused equipment from the Location.</p> <p>It was observed in this inspection that the equipment remains on the Location; no documentation has been submitted by Operator identifying current status/use on Location.</p>		
Corrective Action:	Comply with Rule 606.a and remove equipment not necessary for use on the Location.	Date:	10/02/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:	<p>Inspection #696202916 observed that protection equipment to prevent wildlife access to the secondary containment BMP at the 500 gallon Methanol tank, and the Separator stack were missing or inadequate. Inspection Required Operator to install or repair wildlife protection equipment by 7/18/2021.</p> <p>It was observed in this inspection that protection equipment to prevent wildlife access to the secondary containment BMP at the tank, and separator remain missing or inadequate.</p>		
Corrective Action:	Install or repair wildlife protection equipment	Date:	07/18/2021

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspections observed that BMPs to protect and stabilize unpaved areas of the Location and access road, and to allow for proper stormwater discharge are missing, or insufficient; stormwater runoff resulted in erosion degradation and offsite sediment discharge at Location entrance and access road. Inspection required Operator to comply with Rule 1002.f.(2)C.

It was observed in this inspection that stormwater and erosion control measures remain missing or insufficient at the Location and access road; erosion degradation has persisted.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Ensure control measures are installed in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 07/20/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203325	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5570085">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5570085</a>