

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402856359

Date Received:

11/02/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abigail Wenk

720 644 6997

awenk@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696303687

Inspection Date: 10/15/2021

FIR Submit Date: 10/15/2021

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 323023

Location Name: BASHOR-69N60W Number: 18SWNW County: WELD

Qtrqr: SWN Sec: 18 Twp: 9N Range: 60W Meridian: 6
W

Latitude: 40.750918 Longitude: -104.143250

FACILITY - API Number: 05-123- -00 Facility ID: 244657

Facility Name: BASHOR Number: 18-1

Qtrqr: SWN Sec: 18 Twp: 9N Range: 60W Meridian: 6
W

Latitude: 40.750918 Longitude: -104.143250

CORRECTIVE ACTIONS:

1 CA# 156836

Corrective Action: Comply with Rule 606.c.

Date: 11/01/2021

Response: CA COMPLETED

Date of Completion: 10/28/2021

Operator Comment: Weeds removed. Photos attached.

COGCC Decision: _____

COGCC
Representative:

2 CA# 156837

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/01/2021

Response: CA COMPLETED

Date of Completion: 10/28/2021

Operator Comment: Corrective actions were immediately taken to ensure oily waste disposed of in accordance with 905.e. Lease Operators were immediately notified of the corrective actions required, and service companies were contacted to schedule equipment and soil cleaning activities. Lease Operators inspected equipment and performed the necessary equipment maintenance (e.g. tightening) to ensure the equipment is in good mechanical condition and contaminated soil was removed from the location. Please see attached photos that demonstrate compliance.

COGCC Decision:

COGCC
Representative:

3 CA# 156838

Corrective Action: Comply with Rule 606

Date: 11/01/2021

Response: CA COMPLETED

Date of Completion: 10/28/2021

Operator Comment: Bison Oil & Gas II (Bison) is committed to operating responsibly and prioritizes environmental and safety concerns from COGCC. Bison took immediate action to resolve the Corrective Actions noted by the COGCC inspector and has provided documentaton to demonstrate compliance.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Bison Oil & Gas II (Bison) is committed to operating responsibly and prioritizes environmental and safety concerns from COGCC. Bison took immediate action to resolve the Corrective Actions noted by the COGCC inspector and has provided documentaton to demonstrate compliance.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Abigail Wenk

Signed:

Title: Manager of Compliance

Date: 11/2/2021 12:05:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402856360	Photos - Before
402856361	Photos - After
402859574	waste handling soil manifests

Total Attach: 3 Files