

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402860327

Date Received:
11/02/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

timothy.thomsen@state.co.us

efitzgerald@ogrisop.com

Gee, Greg

903-987-0353

ggee@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201353

Inspection Date: 04/01/2021

FIR Submit Date: 04/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 309477

Location Name: APACHE CANYON-634S67W Number: 4SWSW County: LAS ANIMAS

Qtrqtr: SWS Sec: 4 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.107914 Longitude: -104.897892

FACILITY - API Number: 05-071- -00 Facility ID: 295733

Facility Name: APACHE CANYON Number: 04-13

Qtrqtr: SWS Sec: 4 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.107914 Longitude: -104.897892

CORRECTIVE ACTIONS:

1 CA# 147991

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 05/14/2021

Response: CA COMPLETED

Date of Completion: 10/27/2021

The produced water storage tank was removed from the location. Berm not needed.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 147992

Corrective Action: Install sign to comply with Rule 605.d.

Date: 09/27/2020

Response: CA COMPLETED

Date of Completion: 09/06/2021

Operator
Comment:

The new sign was installed on the separator house.

COGCC Decision:

COGCC
Representative:

3 CA# 147993

Corrective Action: Conduct maintenance on equipment, cleanup stained material, and review self inspection processes.

Date: 04/09/2021

Response: CA COMPLETED

Date of Completion: 08/05/2021

Operator
Comment:

THE DISCOLORATION IN THE SOIL IS A RESULT OF HARDPAN IN THE SOIL. THIS DID NOT ORIGINATE FROM THE PRODUCTION EQUIPMENT. ONCE THE SOIL DRIED, THE DISCOLORED SOIL WAS REMOVED FROM THE WELL PAD SURFACE.

COGCC Decision:

COGCC
Representative:

4 CA# 147994

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/07/2021

Response: CA COMPLETED

Date of Completion: 10/27/2021

Operator
Comment:

THE ROAD SURFACE WAS REGRADED TO ELIMINATE THE TIRE RUTS.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. THE NEW EFORM FORMAT WILL NOT DOWNLOAD ATTACHMENTS--PHOTO LOG DID NOT ATTACH

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: Sr. Environmental Tech.

Date: 11/2/2021 4:32:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files