

TEP  
RMV 36-22  
Location # 335070



Nov 2, 2021 at 10:29:56 AM  
+39.509584,-107.882902 ±4.76m  
COGCC

location



Nov 2, 2021 at 10:32:49 AM  
+39.510143,-107.883969 ±4.68m  
COGCC

location



TEP  
RMV 36-22  
Location # 335070



location



Lack of stabilization/compaction





TEP  
RMV 36-22  
Location # 335070



**Load out line missing cap/bull plug**



**Erosion on access road**





TEP  
RMV 36-22  
Location # 335070



**Erosion on access road**

