

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

11/04/2021

Document Number:

697601661

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
GINTAUTAS, PETER 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
,		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480994	SPILL OR RELEASE	AC	10/27/2021		-	UPRR 43 PAN AM I5	EI

General Comment:

environmental inspection of spill excavation. Opearot staff present wth active excavation and transfer of soils to stockpile were underway.

open excavation at site with approximate dimensions of 31' x 31' x 13 feet deep.

Environmental**Spill/Remediation:**

Comment: site was attended by Operator staff with excavator on site and crew foreman present. excavation was fenced on one side with more fence posts and plastic fencing roll on site. Discussed with foreman that open excavation must be fenced whne they leave site.
Stockpile of soils was being added to and was surrounded on three sides by silt fencing which was in good condition

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601669	hydrocarbon stained soils in excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572017