

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/27/2021

Submitted Date:

10/28/2021

Document Number:

693505679

FIELD INSPECTION FORM

Loc ID 332971 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Revas, Robbie		robbie.revas@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		dnr_cogccenforcement@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	
Gintautas, Peter		peter.gintautas@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239987	WELL	PR	02/01/2021	OW	123-07775	HLADKY-O'GORMAN 3	SI

General Comment:

[Inspection due to complaint Doc #402851160](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not legible not installed properly laying on ground.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Mechanical issue: Electric panel does not have meter installed		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Not corrected will be considered unused equipment.	Date:	
Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules.		
Corrective Action:	Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation	Date:	
Type	OTHER		
Comment:	BMP: Lack of or improper BMP's on location, storage of material and open excavations.		
Corrective Action:	Comply with rule 1002 series.	Date:	
Type	OTHER		
Comment:	Fencing When conducting Remediation activities, Operators will conform to the following standards. Operators will fence or cover open excavations to prevent access when sites are not attended.		
Corrective Action:	Comply with Rule 913 b (5) B i	Date:	
Type	TRASH		
Comment:	Trash on site See photos		
Corrective Action:	Comply with rule 606	Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: earthen berm breached and not repaired Has been documented in inspection reports since 2019				
Corrective Action: ensure adequate secondary containment around the produced water and crude oil storage vessels. Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date:

Venting:

Yes/No	NO
Comment:	<input type="text"/>
Corrective Action:	Date:

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date:

Inspected Facilities

Facility ID: 239987 Type: WELL API Number: 123-07775 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: At time of inspection well is SI due to what appears to be flowline repairs.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/01/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Fail			

Comment: Tracking pad is not adequately maintained to prevent track of material offsite. (Cattle Guard)

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday October 27, 2021 at approximately 11:00AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Hladky-O’Gorman #3 Operator: KP Kauffman API#: 123-07775 County: Weld While there, I observed a well site and what appeared to be an active spill remediation project. During this inspection the following possible compliance issues were observed: Trash: Rule 606 See Photos 3,8,12 Signage: Rule 605 See photo 4 Secondary containment: Rule 9 12 d (1) See photos 14,15 Fencing: Rule 913 b 5 B I See photos 9,10,19 Self inspection: Rule 1002 F (2) Tracking pad: Rule 1002 f (2) F See photos 1,2 Mechanical issue: Rule 608e See photo 3 Weather conditions: Windy After an internal review of recent inspections at KPK facilities, COGCC Staff has determined that KPK has repeatedly and consistently failed to comply with certain COGCC rules (categorized in those inspection reports as violations related to "Signs/Marker," "Emergency Contact Number," and/or "Good Housekeeping"). In light of this apparent pattern of violations, violation(s) identified in this inspection report under those categories are being entered for notification and documentation only and are not intended to provide KPK the potential opportunity to resolve the alleged violation(s) without the imposition of penalty, pursuant to Rule 522.c. Therefore, in this inspection report, COGCC Staff has documented violation(s) and identified relevant corrective action(s) required to return to compliance, and pursuant to Rule 522.c., retains discretion to seek penalties for any violation documented in this inspection report. Pictures and drone flight is attached to inspection.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	10/28/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402857131	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567682
693505680	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567666

693505699

Drone flight.

<http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567667>