

APACHE CANYON 19-14 API# 05-071-08927 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 22, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201754



THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. EXISTING GRAVEL WAS PULLED OUT OF THE BAR DITCH AND THE OUTSLOPE. THIS MATERIAL WAS BLADED BACK ONTO THE ROAD SURFACE. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO IMPROVE STABILIZATION EFFORTS.

APACHE CANYON 19-14 API# 05-071-08927 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 22, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201754



THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. EXISTING GRAVEL WAS PULLED OUT OF THE BAR DITCH AND THE OUTSLOPE. THIS MATERIAL WAS BLADED BACK ONTO THE ROAD SURFACE. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO IMPROVE STABILIZATION EFFORTS.

APACHE CANYON 19-14 API# 05-071-08927 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 22, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201754



THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. EXISTING GRAVEL WAS PULLED OUT OF THE BAR DITCH AND THE OUTSLOPE. THIS MATERIAL WAS BLADED BACK ONTO THE ROAD SURFACE. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO IMPROVE STABILIZATION EFFORTS.

APACHE CANYON 19-14 API# 05-071-08927 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 22, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201754



THE SOUND WALL PANEL THAT WAS ON THE GROUND WAS PLACED BACK INTO USE.

APACHE CANYON 19-14 API# 05-071-08927 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 04, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201754



THE EROSION RILLS ON THE WELL PAD CUT SLOPE WERE FEATHERED OUT AND THE SOIL WAS LEFT IN A ROUGHENED CONDITION. THE DISTURBED SOIL WAS SEEDED BY HAND BROADCAST USING AN APPROVED CPW SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION. EROSION CONTROL BLANKETS WERE INSTALLED FOR SOIL STABILIZATION.