

TEP
RWF 433-10
Location # 335639



location



location

TEP
RWF 433-10
Location # 335639



location



Load out line missing cap/bull plug



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RWF 433-10
Location # 335639



Load out line missing cap/bull plug



Lack of stabilization/compaction



TEP
RWF 433-10
Location # 335639



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RWF 433-10
Location # 335639



Lack of stabilization/compaction



Lack of stabilization/compaction



TEP
RWF 433-10
Location # 335639



Previous inspection photo of erosion on cut slopes



Previous inspection photo of erosion on cut slopes



TEP
RWF 433-10
Location # 335639



Follow up photo of erosion on cut slopes



Follow up photo of erosion on cut slopes

TEP
RWF 433-10
Location # 335639



Follow up photo of erosion on cut slopes



Follow up photo of erosion on cut slopes

TEP
RWF 433-10
Location # 335639



Follow up photo of erosion on cut slopes



Follow up photo of erosion on cut slopes

