

TEP
RMV 89-17
Location # 335063



location



location

TEP
RMV 89-17
Location # 335063



Glycol vessel missing labeling



Load line missing cap/bull plug

TEP
RMV 89-17
Location # 335063



Lack of stabilization/ compaction



location/ Lack of stabilization/ compaction

TEP
RMV 89-17
Location # 335063



Lack of stabilization/ compaction



Lack of stabilization/ compaction



TEP
RMV 89-17
Location # 335063



BMP'S failing off edge of location on N/E side of wells



BMP'S failing off edge of location on N/E side of wells

TEP
RMV 89-17
Location # 335063



BMP'S failing off edge of location on N/E side of wells



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources