

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign not updated to reflect current operator		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	12/16/2021

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 206787 Type: WELL API Number: 013-06282 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection well head was LOTO

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday November 16, 2021 at approximately 2:04PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Hewitt #2-22 Operator: Extraction API#: 013-06282 County: Bolder While there, I observed a SI well site. During this inspection the following possible compliance issues were observed: Sign: Rule 605 g Corrective action date of 12-16-21 Weather conditions: Cloudy and windy A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	11/16/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505891	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5582303