

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402875139

Date Received:

11/18/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51130

Name of Operator: LOCIN OIL CORPORATION

Address: 2445 TECHNOLOGY FOREST BD #710

City: THE WOODLANDS State: TX Zip: 77381

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Nicol, Michael</u>	<u>281-362-8600x116</u>	<u>mnicol@locinoil.com</u>
<u>Thompson, Bud</u>		<u>BLThomps@BLM.gov</u>
<u>Christian, Larry</u>	<u>970-629-5228</u>	<u>larryc@nclnr.com</u>
<u>Benedict, Dan</u>	<u>303-902-1593</u>	<u>dbenedict@arb.energy</u>
<u>Kellerby, Shaun</u>		<u>shaun.kellerby@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 701102215

Inspection Date: 11/16/2021

FIR Submit Date: 11/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION

Company Number: 51130

Address: 2445 TECHNOLOGY FOREST BD #710

City: THE WOODLANDS State: TX Zip: 77381

LOCATION - Location ID: 315416

Location Name: N. DOUGLAS CREEK-61S101W Number: 33NENW County: _____

Qtrqtr: NENW Sec: 33 Twp: 1S Range: 101W Meridian: 6

Latitude: 39.924609 Longitude: -108.740880

FACILITY - API Number: 05-103-00 Facility ID: 315416

Facility Name: N. DOUGLAS CREEK-61S101W Number: 33NENW

Qtrqtr: NENW Sec: 33 Twp: 1S Range: 101W Meridian: 6

Latitude: 39.924609 Longitude: -108.740880

CORRECTIVE ACTIONS:

1 CA# 157937

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/22/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator: _____
Comment: Inspector made the comment "Storm water moving sediment and eroding access road from location to road". Since the initial inspection we graded the location and the BLM road immediate adjacent to the location. We also filed a FIRR; Document #402807418. The response was Not Approved and the reason provided was "No documentation was provided by operator". Attached is a picture of the BLM road (identified in yellow) and its location adjacent our location. There is NOT an access road from the BLM road to the location. The BLM road appears to run through the north side of the location; however, the north edge of our location is designated by the dead man on the north side of the location. We respectfully request a Decision that the necessary action was completed prior to this inspection. If the Decision is Not Approve, we respectfully request a site visit with the COGCC Supervisor to understand and discuss the inspector's determination of the "access road from location to road".

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see operator comment on the Corrective Action Item #1

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael J Nicol

Signed: _____

Title: Manager

Date: 11/18/2021 4:37:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccwebblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402875200	BLM Road adjacent to NDC #3-33 location
-----------	---

Total Attach: 1 Files