

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2021

Submitted Date:

11/22/2021

Document Number:

688801032

FIELD INSPECTION FORMLoc ID 325388 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7650

Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	
Fischer, Alex		alex.fischer@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115780	PIT				-	LA POSTA CANYON 4	EI
214687	WELL	PR	10/01/2020	GW	067-06291	LA POSTA CANYON 4	EI

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer La Posta Canyon #4. For the most recent field inspection report of this facility, please refer to document #693903445. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was performing work associated with REM #20746.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	PA marker has been welded on.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign mounted to meter house.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PBV sign has been removed with fencing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted on location signs.	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		100 BBLS			37.136768,-107.952347
Comment:					

Corrective Action:		Date:	
<u>Paint</u>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<u>Berms</u>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:		Date:	
<u>Wells Served By Facilities Above</u>			
API Number		AirsID	
067-06291			
<u>Venting:</u>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	115780	Type:	PIT	API Number:	-	Status:		Insp. Status:	EI
Facility ID:	214687	Type:	WELL	API Number:	067-06291	Status:	PR	Insp. Status:	EI

Environmental	
Spill/Remediation:	
Comment:	Work is proceeding under REM #20746 to decommission location.
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB):	
Comment:	<div></div>
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType: Lined: Pit ID: 115780 Lat: 37.138437 Long: -107.950871Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

Pit Facility ID #115780, related to the La Posta Canyon #4, has an unknown status in the COGIS database.

Corrective Action:

The operator will submit a Form 27 Site Investigation and Remediation Workplan, required by Rule 913.c., to close Pit Facility ID #115780.

Date: 12/22/2021**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer La Posta Canyon #4. For the most recent field inspection report of this facility, please refer to document #693903445. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was performing work associated with REM #20746. The PBV contained fluids and was unable to be moved at the time of this inspection. The wellhead had been cut off and a PA marker welded on. Flow lines were to be excavated and removed at a later date. Equipment from the BMG Drilling La Posta Canyon #2 was being temporarily stored on location to make room for PA operations on that location.	hughesjo	11/22/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801033	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587928