

Inspection Photos
Location Name: La Posta #3R
API: 05-067-07915



Location berm has been breached.



Sediment is being transported onto location from the cut slope.

Inspection Photos
Location Name: La Posta #3R
API: 05-067-07915



Thief hatch is open on left AST. Signs and placards are not compliant with Rule 605.h.



Rip rap BMP has filled in with sediment.