

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402862350

Date Received:
11/04/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 4 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1001 17TH STREET #1900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Christina Pierce</u>	<u>970-263-3626</u>	<u>cpierce@Laramie-Energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203156

Inspection Date: 09/09/2021

FIR Submit Date: 09/13/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1001 17TH STREET #1900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335643

Location Name: Cascade Creek Number: 697-16-28 County: _____

Qtrqr: SENW Sec: 16 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.524160 Longitude: -108.225175

FACILITY - API Number: 05-045- -00 Facility ID: 335643

Facility Name: Cascade Creek Number: 697-16-28

Qtrqr: SENW Sec: 16 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.524160 Longitude: -108.225175

CORRECTIVE ACTIONS:

2 CA# 155766

Corrective Action: Operator shall provide documentation and figures showing the location of where the topsoil is being stored for final reclamation, and how much (cu. yards).

Date: 09/17/2021

Submit documentation to Reclamation Specialist attached to a Form 4 Sundry

Response: CA COMPLETED

Date of Completion: 11/03/2021

Operator Comment: Hand dug a series of 24 small test holes on the top soiled portion of the CC 697-16-28 pad. Based on those results, the pad has an average depth of topsoil of 4 inches on the northeast side of the location. Four inches spread over that area works out to approximately 550 cubic yards of topsoil on location.

COGCC Decision: Approved

COGCC Representative: Corrective action required Operator to identify how much topsoil is being stored for final reclamation, and its Location. Operator certifies and states within this resolution that there is 550 cubic yards of topsoil on the northeast side of the Location; Operator has also provided additional figures showing the Location of the topsoil, as well as a "Construction Lay Drawing" (dated 2/17/2011) for the southern section of the Location.

It is noted that Operator failed to follow the corrective action and submit the required documentation attached to a Form 4.

It is also noted, based on the calculations provided, that topsoil salvage does not appear to have been conducted in accordance with COGCC 1002 Rules, and the amount of topsoil currently stored (550 cubic yards) appears insufficient for future reclamation of the Location.

Additional review of the issue is being conducted internally.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce Signed: _____

Title: Engineering Tech Date: 11/4/2021 11:26:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402862350	FIR RESOLUTION SUBMITTED
402862353	corrective action
402862355	corrective action
402862356	corrective action

Total Attach: 4 Files