

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402792340

Date Received:

08/26/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jones, Tammy

tajones@hilcorp.com

Shorty, Priscilla

pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903545

Inspection Date: 08/10/2021

FIR Submit Date: 08/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326206

Location Name: HUBER-RIDDLE-N35N8W Number: 27NWSE County: LA PLATA

Qtrqr: NWSE Sec: 27 Twp: 35N Range: 8W Meridian: N

Latitude: 37.272970 Longitude: -107.728270

FACILITY - API Number: 05-067-00 Facility ID: 216041

Facility Name: HUBER-RIDDLE Number: 1-27

Qtrqr: NWSE Sec: 27 Twp: 35N Range: 8W Meridian: N

Latitude: 37.272970 Longitude: -107.728270

CORRECTIVE ACTIONS:

1 ☒ CA# 154885

Corrective Action: -Remove and properly store or dispose of fencing debris by 9/16/2021.

Date: 09/16/2021

Response: CA COMPLETED

Date of Completion: 08/25/2021

Operator Comment: Debris on location removed. See attached photo.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 154886

Corrective Action: -Flowering musk thistles need to be cut and removed by 8/28/2021. Control weeds.
Corrective action timing is reduced to prevent seed dispersal of flowering weeds.

Date: 08/28/2021

Response: CA COMPLETED

Date of Completion: 08/25/2021

Operator
Comment: Thistles removed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 154887

Corrective Action: -Stormwater controls need to be installed to prevent sediment discharge from the
project area, by 9/16/2021.

Date: 09/16/2021

Response: CA COMPLETED

Date of Completion: 08/25/2021

Operator
Comment: Erosion controls installed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 8/26/2021 6:03:38 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402792340	FIR RESOLUTION SUBMITTED
402792344	Huber-Riddle 1-27_Resolved Photos

Total Attach: 2 Files