

TEP
RMV 20-35
Location # 323894



location



location

TEP
RMV 20-35
Location # 323894



location



Glycol vessel not properly labeled, as seen in sight glass the fluid.

TEP
RMV 20-35
Location # 323894



Load lines missing bull plugs/caps



Load lines missing bull plugs/caps